

Vehicle Diagnostic Report

Vehicle Information

Make:TESLA

VIN:5YJ3E7EBXLF780757

Vehicle Software Version:V10.60

Diagnostic Application Version:V8.00.041

Diagnostic path:Automatically Search > Model 3 > Health Report

Repair Shop

Shop Name:

Address:

Zip Code:

Telephone:

Email:

SN:987807203454

Test Time:2026-03-08 12:43:59



System fault code 【Pre-Repair】

The following systems are OK:

- 1.BMS (Battery Management System)
- 2.CP (Charging Port)
- 3.EPBL (Left Electronic Parking Brake)
- 4.EPBR (Right Electronic Parking Brake)
- 5.HVP (High Voltage Processor)
- 6.PCS (Power Conversion System)
- 7.PTC (Positive Temperature Coefficient)
- 8.SCCM (Steering Column Control Module)
- 9.VCFRONT (Body Control Module)
- 10.VCLEFT (Left Body Control Module)
- 11.VCRIGHT (Right Body Control Module)
- 12.SEC (Security Controller)

Disclaimer

This inspection report is for vehicle maintenance reference only. The vehicle operation data provided in this report are static data. Detailed dynamic diagnostic data can be read using professional maintenance equipment. We are not responsible for any accidents or malfunctions caused thereby!